


LEAK LOCATOR + PLUS

IDENTIFY LEAKS



IDEAL FOR ALL GAS LEAK DETECTION



- NON-CORROSIVE
- BIO-DEGRADABLE
- HIGH VISIBILITY
- EASY FLOW
- LONG LASTING BUBBLES

Location of leaks on pressurized lines, fitting and containers. Formation of bubbles indicates loss of gas. Formation of bubbles indicates leaks. Protect Packaging against frost. When using on polyamide lines, wash off product with water afterwards.

DIRECTION FOR USE

1. Shake the bottle before use.
2. Spray from a distance of 5-30 cm onto the surface/Joints to be tested.
3. Large leaks bubble start to grow immediately; slow, small leaks bubble growth visible within a few seconds or minutes.
4. When leak detection has been completed, wipe inspected surface with a damp cloth.

1. SHAKE



2. SPRAY



3. INSPECT



4. CLEAN



FOR INDUSTRIAL USE ONLY

Test Compatibility With The Painted Or Coated Surfaces, Plastic And Rubbers Prior To Application

LEAK LOCATOR PLUS *Ultra*

FINDING MICRO LEAKS IS EASY NOW

Best solution for pin pointing all types of gas leak. For use on Pneumatic & gas system as well as refrigerating machine. Formation of bubbles indicates leaks.

DIRECTION FOR USE

1. Avoid shaking the bottle before use.
2. Gently apply with applicator on the required surfaces/ joints.
3. Do not brush up a lather, always apply the fluid as a clear liquid.
4. Large leaks bubble start to grow immediately, slow & small leaks bubble growth visible within a few secs & minutes or more/hour.
5. When leak detection has been completed, rinse inspected surface through water.



1. APPLY



2. INSPECT



3. CLEAN



Test Compatibility With The Painted Or Coated Surfaces, Plastic And Rubbers Prior To Application